

Date: Thursday, 15/05/2008 11:44:20 AM
 User: Julie Lecocq

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: D412-630-023 /-024
Job Number	: 39285	Part Number	: <i>Ant Scrap</i> SCRAP15
Estimate Number	: 10804	Drawing Number	: R08-048
P.O. Number	:	Project Number	:
This Issue	: 15/05/2008	S.O. No.	:
Prsht Rev.	: NC	Drawing Revision	:
First Issue	: / /	Type	: LARGE FAB ASSY
Previous Run	: 00015	Material	:
Written By	:	Due Date	: 22/05/2008
Checked & Approved By	: <i>JUD 08.5.15</i>	Qty:	6 Um: Each
Comment	:		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
----------------	------------------------------	----------------------

1.0	D412630023	Heli Access Step LH Folding
-----	------------	-----------------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 6.0000 Each(s)
 Heli Access Step LH Folding
 2x B22509
 1x B22507

2.0	D412630024	Heli Access Step RH Folding
-----	------------	-----------------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 6.0000 Each(s)
 Heli Access Step RH Folding
 1x B22510
 1x B22508
~~1x B~~

3.0	LARGE FAB 1	LARGE FABRICATION RESOURCE 1
-----	-------------	------------------------------



Comment: LARGE FABRICATION RESOURCE 1
 Steps are the old revision, and are scrapped due to cracked welds.
 Scrap and destroy.

4.0	QC5	INSPECT WORK TO CURRENT STEP
-----	-----	------------------------------



Comment: INSPECT WORK TO CURRENT STEP

5.0	QC21	FINAL INSPECTION/W/O RELEASE
-----	------	------------------------------



Comment: FINAL INSPECTION/W/O RELEASE

08/07/25

MF 06-07-2